

ACIDENT CLASSIFICATION												DATE 29.6.43		TIME 0205		COMMAND			
UNIT 37 S.F.T.S. Calgary				COM. 4		PLACE R.l, Airdrie				H.Q. FILE 1300-AJ.977									
A/C TYPE Harvard II Harvard II				No. AJ.969 AJ.977		CRASH CAT. C.3 C.10		S.E. X		M.E.		DAY		NIGHT X					
PERSONNEL				RANK		NUMBER		DUTY		INJURIES		SIGNAL							
Gilham, N.A.C. (AUS)				LAC		418265		PP		Nil		No.		DATE					
Cross, J.J. (AUS)				LAC		424121		PP		Nil		A91		29.6					
												D 14 (REVISED)							
												No.		CHECKED					
												15		X					
												#140							
ENGINE				ENGINE NUMBER (S)				HOURS FLOWN BY PILOTS											
Wasp				4819/11603 Nil				INST.		NIGHT		ON TYPE		TOTAL					
Wasp				4588/9029 Nil								SOLO		DUAL		SOLO		DUAL	
						28		14		47		63		76		95			
						28		11		45		69		74		99			
ACIDENT CLASSIFICATION												STAGE OF FLIGHT		MONTH		COMMAND			
												FORCED LANDING		7		4			
												TAXIING		1		2			
												LANDING				1			
												TAKE-OFF				2			
												FLIGHT				7			
												STATRY				1			
												FATAL				2			
												INJURY				4			
												3RD				1			
												2ND				2			
												1ST				1			

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Night circuits and landings.

Nil

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

When taxiing at night to taxiing post, pupil of AJ969 taxied into AJ977 which was stationary waiting permission to take-off.

FINDINGS:

SUMMARY No.



CLASSIFICATION:

~~3. Hitting other aircraft.~~ 9

COLLISIONS.

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

ACTION TAKEN:

Log book endorsed and awarded 7 days C.B.