

CASPIR ARCHIVAL METADATA

Serial:	10705
Title:	Fairchild Cornell Mk. II serial:10705 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1943-June-10. Cornell II s/n 10705. This accident involved 2 people. Mortimer AC, Rawson CA
Keywords:	RCAFCornell II,10705,2 FIS,2 Flying Instructor School,Aerodrome,1943-June-10,Mortimer,RawsonRCAF L20
Created:	1943-06-10
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#10705

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 2 F.I.S. Pearce, Alta.		COM. 4	PLACE H.A.		DATE 1-6-43	TIME 1645			
A/C TYPE Cornell 11		No. 10705	CRASH CAT. C 1	S.E. X	M.E.	DAY X NIGHT			
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Rawson, C.A.		F/O	J12089	FI	NIL.		No.	DATE	
Mortimer, A.C. GB		S/P	1324953	PP	NIL.		A223	12-6	
							D 14 (REVISED)		
							No. 2	CHECKED <input checked="" type="checkbox"/>	
							#11		
ENGINE		ENGINE NUMBER(S)		HOURS FLOWN BY PILOTS					
Ranger 6333/27540		NIL.				ON TYPE		TOTAL	
				INST.	NIGHT	SOLO	DUAL	SOLO	DUAL
				-	-	107	7	1311	120
				-	-	47	5	107	140

COMMAND

MONTH

STAGE OF FLIGHT

4
2
1
7
4
2
1
1
FORCED LANDING
TAXIING
LANDING
TAKE OFF
FLIGHT
STAIRY
FATAL
INJ
INJURY
3RD
5
RAE
M 2

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PURPOSE OF FLIGHT:

Instruction.

TECHNICAL OFFICER'S REPORT:

Nil. *TCO/PC7/WVCO ✓*

NATURE OF ACCIDENT:

A/C collided with steam roller while taxiing in heavy rain and poor visibility.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~2. Hitting obstructions.~~ *9*
9. Collisions

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

ACTION TAKEN:

Nil.