

ACCIDENT CLASSIFICATION

UNIT 2 BCG School MossBank	COM. 4	PLACE H.A.	DATE 15-6-43	TIME 1310
A/C TYPE Anson II Bolingbroke 117		NO. 7725 D 99A5	CRASH CAT. C 2 C	H.Q. FILE 1100-77-25
		S.E.	M.E.	DAY
			X	X
		NIGHT		

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Johnson, C.L.	WO2	R36735		NIL.	NO.	DATE
Byers, J.A. GB	Lac.	1098512		NIL.	A15	15-6
Brexina, F.G.	Lac.	R84002	AB	NIL.	D 14 (REVISED)	
Farr, T.O.	AO1	R202784	TD	NIL.	NO.	CHECKED
						<input checked="" type="checkbox"/>
					#22	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
Jacobs L6MB	25906/19794 Nil	INST.	NIGHT	ON TYPE		TOTAL	
	25479/14168 Nil			SOLO	DUAL	SOLO	DUAL
Mercury	2925/856997 Nil	34	72	268	8	677	146
	2980/856980 Nil						

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT BR
FATAL
INJ. 3rd
INJ. 5th
RAF M N

PURPOSE OF FLIGHT:

Routine bombing exercise.

TECHNICAL OFFICER'S REPORT:

No technical defect.

DEVI
TCA/PCT
MA/XM

NATURE OF ACCIDENT:

While attempting to park a/c in restricted space, rudder of Anson 7225 struck stbd elevator of Bolingbroke 9915 damaging both planes.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other aircraft.~~

COLLISIONS.

9

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

ACTION TAKEN:

Log book endorsed.