

CASPIR Aircraft Accident Cards

Serial: 725 (linked to FP725)

Title: Avro Anson Mk. II serial:FP725 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-June-27. Anson II s/n 725 (linked to FP725). This accident involved 1 person. Millichip DW

Keywords: RCAFAnson II,725 (linked to FP725),7 SFTS,7 Service Flying Training School,Aerodrome,1943-June-27,MillichipRCAF L20

Created: 1943-06-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP725>

PURPOSE OF FLIGHT:

Training circuits.

TECHNICAL OFFICER'S REPORT:

No technical failure involved.

NATURE OF ACCIDENT:

Overshot in no wind conditions. Turned at end of runway with excessive speed, collapsing undercarriage and damaging both propellers.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~29. Overshooting runway.~~ /

OVERSHOT.

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

~~25. Inexperience.~~

v/c STRAIN.

34

ACTION TAKEN:

Pilot's Log Book endorsed.
Awarded 7 days C.B.