



PURPOSE OF FLIGHT:

Solo practice take-offs and landings.

NATURE OF ACCIDENT:

Lac. East in A/C 5063 had turned left after landing to watch for incoming traffic. Lac. Stewart in A/C 4254 collided into port side of A/C 5063 during the landing run.

CLASSIFICATION:

~~45. Collision.~~

*COLLISIONS. 6*

SECONDARY OR CONTRIBUTORY FACTORS:

~~25. Inexperience.~~

TECHNICAL OFFICER'S REPORT: *Nil.*

Nil.

*LCA/50*  
*LCA/110*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Log book endorsed and Lac. Stewart to be flight tested.