

TYPE OF A/C		UNIT 35 S.F.T.S. No. Battleford		COM. 4	PLACE Alvena, Sask.		DATE 15.6.43	TIME 1155	COMMAND					
		A/C TYPE Oxford II		No. BM.677	CRASH CAT. G7	H.Q. FILE 1300-BW.677		S.E.		M.E. X	DAY X	NIGHT		
TYPE OF UNIT	PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL		MONTH			
	Webb, F.E.			LAC	1683567	PP	Nil		No.	DATE		STAGE OF FLIGHT		
	Spencer, J.J.			Cpl	920715	PP	Nil		A680	15.6				
									D 14 (REVISED)					
CATEGORY	ENGINE			ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS						STAGE OF FLIGHT		
	Cheetah X			157532/178492		ON TYPE		TOTAL						
			INST.	NIGHT	SOLO	DUAL	SOLO	DUAL	SOLO	DUAL	INJURY			
			22	9	30	53	64	103	21	11			34	47
		21	11	34	47	66	100					3RD		

ACCIDENT CLASSIFICATION

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKEOFF
FLIGHT
STATRY
FATAL
INJURY
3RD
RAJ
M N

102

61

60

59

58

57

56

55

54

53

52

51

50

49

48

47

46

45

44

43

42

41

7

4

2

1

7

4

2

1

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

RAJ

M N

PURPOSE OF FLIGHT:

Navigation cross country.

TECHNICAL OFFICER'S REPORT:

Water was found in both fuel filters.

NATURE OF ACCIDENT:

Engine failed, A/C force landed.
A/C swung A/C to port to avoid
hitting boundary road, port leg
collapsed.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

FB / 201 / 2 / 110 / M / 1

CLASSIFICATION:

~~54. Engine failure in the air.~~ 17
17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

~~31. Wheels down but not fully locked.~~
*26. Engine trouble -
accident.* 26

ACTION TAKEN:

Nil.