

CASPIR Aircraft Accident Cards

Serial: 2869

Title: North American Harvard Mk.II serial:2869 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-July-02. Harvard II s/n 2869. This accident involved 2 people. Shields DM, Vandenbrande RA

Keywords: RCAFHarvard II,2869,1 SFTS,1 Service Flying Training School,Aerodrome,1943-July-02,Shields,VandenbrandeRCAF L20

Created: 1943-07-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2869>

PURPOSE OF FLIGHT:

Seq. 6-7-8

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Student overcontrolled in effort to correct swerve. Instructor took over control but not soon enough to prevent ground loop.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.



CLASSIFICATION:

~~61. Swinging on landing~~

2. Swung.

(2)

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground Loop~~

ACTION TAKEN:

Log book endorsed.