

CASPIR Aircraft Accident Cards

Serial: FE872

Title: North American Harvard Mk. IIB serial:FE872 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-July-07. Harvard IIB s/n FE872. This accident involved 1 person. Banister J

Keywords: RAFHarvard IIB,FE872,34 SFTS,34 Service Flying Training School,Aerodrome,1943-July-07,BanisterRCAF L20

Created: 1943-07-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE872>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE Main Aerodrome	DATE 7-7-43	TIME 1820
A/C TYPE Harvard IIB	No. FE872	CRASH CAT. D.1	H.Q. FILE 1300-FE872	
			S.E. X	M.E. DAY X
				NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Banister, J.	P.O.	49769	PP	Nil	No.	DATE
<p><i>Incident</i></p>					D 14 (REVISED)	
					No.	CHECKED
					7/9	X
					40	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp R1340AM1	21100/42-1176 IM1			7	14	50	59

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

- 7
- 4
- 2
- 1
- 7
- 4
- 2
- 1
- 1
- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STATIONARY
- FATAL
- INJ
- INJURY
- 3RD
- 5
- RAF
- M
- N

1 P2
 2
 3
 4
 5
 6
 7
 8
 9
 10
 11
 12
 13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 A
 B
 C
 D
 E
 F
 G
 H
 I
 J
 K
 L
 M
 N
 O
 P
 Q
 R
 S
 T
 U
 V
 W
 X
 Y
 Z

PURPOSE OF FLIGHT:

Solo exercises

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pupil landing on runway with considerable drift, bounced, port wing dropped when A/C touched down again.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

40. Heavy landing - flying into ground.

SECONDARY OR CONTRIBUTORY FACTORS:

17. Disobedience of standing orders.

ACTION TAKEN:

Log book endorsed "Inexperience"