

CASPIR Aircraft Accident Cards

Serial: AJ936

Title: North American Harvard Mk. II / 2 serial:AJ936 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-July-12. Harvard II s/n AJ936. This accident involved 1 person. Williams SM

Keywords: RAFHarvard II,AJ936,41 SFTS,41 Service Flying Training School,Aerodrome,1943-July-12,WilliamsRCAF L20

Created: 1943-07-12

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ936>

ACCIDENT CLASSIFICATION												
TYPE OF A/C	UNIT No. 41 S.F.T.S. Weyburn, Sask.		COM. # 2	PLACE M.A.				DATE 12-7-43	TIME 1140		COMMAND	A 2 1 7 4 2 1
	A/C TYPE Harvard II		NO. AJ936	CRASH CAT. C 2		S.E. X	M.E.	DAY X	NIGHT	H.Q. FILE 1300-AJ936		
TYPE OF UNIT	PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		MONTH	4 2 1 4 2 1	
	Williams, S.M.		LAC	1509333	PP	Nil		NO. A122	DATE 13-7			
								D 14 (REVISED)				
								NO. 8	CHECKED X			
CATEGORY	ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				STAGE OF FLIGHT		43	3 2 1 4 2 1 5 3RD 5 N
	Wasp S3H1		10523/A.213518 Nil		INST. 8	NIGHT 5	ON TYPE		TOTAL			
							SOLO 7	DUAL 13	SOLO 39	DUAL 61		
ACCIDENT CLASSIFICATION												

COMMAND

MONTH

STAGE OF FLIGHT

Forced Landing
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY

RAF M N

) PURPOSE OF FLIGHT:

) Steep turns and forced landings

) NATURE OF ACCIDENT:

) A/C swung on landing and port wing touched runway.

) TECHNICAL OFFICER'S REPORT:

Nil

) COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

) FINDINGS:

) SUMMARY No.

) CLASSIFICATION:

) ~~61. Swinging on landing~~

) ~~1 Swung~~

(2)

) SECONDARY OR CONTRIBUTORY FACTORS:

) ~~38. Ground Loop~~

) ~~25. Inexperience~~

) ACTION TAKEN:

Nil