

CASPIR Aircraft Accident Cards

Serial: 2876

Title: North American Harvard Mk.II serial:2876 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-July-18. Harvard II s/n 2876. This accident involved 1 person. Price GA

Keywords: RAFHarvard II,2876,41 SFTS,41 Service Flying Training School,R1 Halbrite,1943-July-18,PriceRCAF L20

Created: 1943-07-18

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2876>

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT No. 41 S.I.T.S. Weyburn, Sask.	COM. # 2	PLACE Ft. Halbrite	DATE 18-7-43	TIME 0945
A/C TYPE Harvard II	NO. 2576	CRASH CAT. C 5	H.Q. FILE 1100-28-76	
			S.E. X	M.E. DAY X NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Price, G.A.	SGT	1213310	P	111	NO. A123 DATE 19-7
					D 14 (REVISED)
					NO. 12 CHECKED ✓
					63

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	SERIOUS	HOURS FLOWN BY PILOTS					
			INST	NIGHT	ON TYPE			
Wasp S3HL	8515/4374	Serious			SOLO	DUAL	SOLO	DUAL
			43	27	156	76	231	152
					232		383	

4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKEOFF
FLIGHT
STATRY
FATAL
INJURY
3RD
5
RAF
M N

TYPE OF A/C
TYPE OF UNIT
CATEGORY
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PURPOSE OF FLIGHT:

) Returning to R.1 from Main Aerodrome

TECHNICAL OFFICER'S REPORT:

) Ground has been carefully examined and no soft spots)
) could be found.)

NATURE OF ACCIDENT:

) Staff pilot landing thought his land-
) ing run excessively long and applied
) brakes, nosing over.)

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

) Medical Officer's examination shows a visual
) defect in pilot which is being inquired into
) and investigated.)

CLASSIFICATION:

) ~~4. Harsh use of brakes~~

) *1 Other*

(7)

SECONDARY OR CONTRIBUTORY FACTORS:

) ~~37. Overturning~~

) ~~32. Pilot Error~~

) ~~57. Miscellaneous~~

ACTION TAKEN:

) Awaiting result of eye test.)