



PURPOSE OF FLIGHT:

Solo exercises.

TECHNICAL OFFICER'S REPORT:

Tail wheel burst after life of 81 hours 5 mins.

NATURE OF ACCIDENT:

Tail wheel tyre burst while taxiing to take-off position.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

57. Miscellaneous.

SECONDARY OR CONTRIBUTORY FACTORS:

33. Technical defect.

15. Tire failure.

ACTION TAKEN:

MIL