

CASPIR Aircraft Accident Cards

Serial: JS166

Title: Avro Anson Mk. II serial:JS166 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-July-22. Anson II s/n JS166. This accident involved 2 people. Everett VHH, Morrow HF

Keywords: RCAFAnson II,JS166,19 SFTS,19 Service Flying Training School,Rosemary Alberta,1943-July-22,Everett,MorrowRCAF L20

Created: 1943-07-22

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#JS166>

PURPOSE OF FLIGHT:

Low flying cross country.

TECHNICAL OFFICER'S REPORT:

Cause obscure, but believe fractured or broken fuel line was responsible for fire.

NATURE OF ACCIDENT:

Port engine caught fire in the air, landed straight ahead wheels up. A/C burned completely. Fire extinguisher used.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

BE / 301 / ET / 44 / 12 / 46 / GA

CLASSIFICATION:

~~27. Fire in the air.~~ 17

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

34. Wheels up landing.

28. Fire in Air. 28

ACTION TAKEN:

NIL