

CASPIR ARCHIVAL METADATA

Serial:	11297
Title:	Avro Anson Mk. II serial:11297 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1943-July-23. Anson II s/n 11297. This accident involved 1 person. Burchill JG
Keywords:	RCAFAnson II,11297,8 BGS,8 Bomb & Gunnery School,Aerodrome,1943-July-23,BurchillRCAF L20
Created:	1943-07-23
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11297

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62																																																																																																																																																	
ACCIDENT CLASSIFICATION																																	DATE 23-7-43			TIME 1600			COMMAND																																																																																																																																																																							
UNIT 8 B&G School Lethbridge			COM. 4			PLACE L.A.						H.Q. FILE 1100-112-97			A/C TYPE Anson 11			NO. 11297			CRASH CAT. C 7			S.E.			M.E. X			DAY X			NIGHT			MONTH																																																																																																																																																																										
PERSONNEL			RANK			NUMBER			DUTY			INJURIES			SIGNAL			NO.			DATE			D 14 (REVISED)			NO.			CHECKED			STAGE OF FLIGHT																																																																																																																																																																													
Burchill, J.G.			P/O			J26989			P			Nil.			4-228			23-7			7			✓			37			FORCED LANDING																																																																																																																																																																																
ENGINE			ENGINE NUMBER (S)						HOURS FLOWN BY PILOTS						ON TYPE			TOTAL						LANDING																																																																																																																																																																																						
Jacobs L6MB			25997/10701			Nil			INST.			NIGHT			SOLO			DUAL			SOLO			DUAL			FLIGHT																																																																																																																																																																																			
			25984/10688			Nil			39			16			1			3			667			92			STATRY																																																																																																																																																																																			
CATEGORY			D			C			B			A			V			R			1			2			3			4			5			6			7			8			9			10			11			12			13			14			15			16			17			18			19			20			21			22			23			24			25			26			27			28			29			30			31			32			33			34			35			36			37			38			39			40			41			42			43			44			45			46			47			48			49			50			51			52			53			54			55			56			57			58			59			60			61			62		
ACCIDENT CLASSIFICATION																																	INJ.			3rd			INJURY			FATAL			FLIGHT			STATRY			FLIGHT			TAKE-OFF			LANDING			TAXIING			FORCED LANDING			MONTH																																																																																																																																												

PURPOSE OF FLIGHT:

) Circuit Practice

NATURE OF ACCIDENT:

) U/C would not lock down. When pilot
) landed, A/C rolled along runway un-
) til almost to a stop and then the
) wheels retracted.

TECHNICAL OFFICER'S REPORT:

U/C locks apparently failed. Cause of failure under investigation.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

100/200

CLASSIFICATION:

) ~~31. U/C down but not fully locked.~~

) 31. U/C Failure

5

SECONDARY OR CONTRIBUTORY FACTORS:

) ~~33. Technical Defect.~~

) 33. U/C Defect

35

ACTION TAKEN:

Nil