

TYPE OF A/C		ACCIDENT CLASSIFICATION		DATE 3.7.43		TIME 0930	
		UNIT 9 B.G.S. Mont Joli	COM. 3	PLACE 1 mile SW of Bic, P.Q.	H.Q. FILE 1100-74-5		
A/C TYPE Battle (Turret)		NO. 7405	CRASH CAT. C.8	S.E. X	M.E.	DAY X	NIGHT
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		
Savoie, L.A.		WO2	R113547	P	Nil		
Brown, H.M.		LAC	R166925	AG	Nil		
Goodman, R.M.		LAC	R167209	AG	Nil		
TYPE OF UNIT					SIGNAL		
					NO.	DATE	
					N.52	4.7	
					D 14 (REVISED)		
					NO.	CHECKED	
					1	☒	
					#1		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS			
Merlin III		8014/3683 Slight.				ON TYPE	
				INST.	NIGHT	SOLO	DUAL
				28	14	500	2
CATEGORY				TOTAL			
				SOLO	DUAL	SOLO	DUAL
						670	96

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATUTORY
FATAL
INJURY
3RD
RAI
M 2

PURPOSE OF FLIGHT:

Scheduled camera gun exercise.

TECHNICAL OFFICER'S REPORT:

NATURE OF ACCIDENT:

At 2300 ft. engine failed and cockpit was filled with black smoke. Tried to re-start engine but could not succeed, selected a field, pump his flaps down and cut out the switches. The landing was effected in a small field.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

17. Forced Landing

17

SECONDARY OR CONTRIBUTORY FACTORS:

34. wheels up landing

26. Engine Trouble - Accident

ACTION TAKEN:

Nil

26