

ACCIDENT CLASSIFICATION

UNIT No.124 Ferry Sqn., Rockcliffe	COM. APHQ	PLACE Stevenson's Airport Winnipeg, Man.	DATE 12-7-43	TIME 1130				
	A/C TYPE Bolingbroke Anson	NO. 10250 6237	CRASH CAT. C C	H.Q. FILE 1100-102-50				
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL		
Later, J.D.		F/S	R118139	P	Nil	No.	DATE	
Whatley, D.H.		LAC	R98688	OC	Nil	Q740	12-7	
						D 14 (REVISED)		
						No.	CHECKED	
						5	<input checked="" type="checkbox"/>	
						No. 6		
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Mercury XX	S.12731	Nil	INST.	NIGHT	ON TYPE		TOTAL	
	P.12578	Nil			SOLO	DUAL	SOLO	DUAL
			36	18	48	1	917	97
Jacobs	S.109690	Nil						
	P.10827	Nil						

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY
5
M
N

102
61
60
59
58
57
56
55
54
53
52
51
50
49
48
47
46
45
44
43
42
41
40
39
38
37
36
35
34
33
32
31

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
RAF
M
N

PURPOSE OF FLIGHT:

Ferrying aircraft.

TECHNICAL OFFICER'S REPORT:

No evidence of technical failure.

NATURE OF ACCIDENT:

Stbd. wing of Bolingbroke struck nose of Anson causing damage to front of Anson and to stbd. aileron of Bolingbroke. Braking action of Bolingbroke was not enough to stop in time.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

3. ~~Hitting other aircraft.~~

9. *Collision*

SECONDARY OR CONTRIBUTORY FACTORS:

~~1. Bad surface of aerodrome~~

~~32. Pilot error.~~

ACTION TAKEN:

Pilot's Log Book endorsed.