

PURPOSE OF FLIGHT:

653 - Training (12 Comm. Sqn.)
SH921 - Taxiing back to hangar

TECHNICAL OFFICER'S REPORT:

No technical failure.

7/27/12
7-27/12

NATURE OF ACCIDENT:

Cornell attempted to pass parked A/C on taxi strip which was carrying out preliminary cockpit check prior to take off.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other aircraft.~~ 9

9. collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

ACTION TAKEN: