



PURPOSE OF FLIGHT:

Solo practice.

TECHNICAL OFFICER'S REPORT:

No technical failure involved.

NATURE OF ACCIDENT:

Pupil failed to keep straight during landing run, and A/C ground looped.

LS/153

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~61. Swinging.~~

2. Swinging.

(2)

SECONDARY OR CONTRIBUTORY FACTORS:

~~25. Inexperience.~~

ACTION TAKEN:

NIL