

CASPIR Aircraft Accident Cards

Serial: FE343

Title: North American Harvard Mk. IIB serial:FE343 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-August-02. Harvard II s/n FE343. This accident involved 1 person. Walsh KE

Keywords: RAFHarvard II,FE343,41 SFTS,41 Service Flying Training School,R1 Halbrite,1943-August-02,WalshRCAF L20

Created: 1943-08-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE343>

PURPOSE OF FLIGHT:

Solo training.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pilot landed halfway up aerodrome in light wind and used brakes too harshly.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

L0/PSO ✓

CLASSIFICATION:

~~29. Overshooting runway.~~ /

1. *Overshot*

SECONDARY OR CONTRIBUTORY FACTORS:

~~4. Harsh use of brakes.~~

ACTION TAKEN:

Log book endorsed "Carelessness".