


ACCIDENT CLASSIFICATION

UNIT	13 S.F.T.S. St. Hubert		COM.	3		PLACE	M.A.		DATE	11-8-43		TIME	1500	
	A/C TYPE	Harvard II Harvard II		NO.	FE861 FS668 D		CRASH CAT.	C1 Nil		S.E.	M.E.		DAY	NIGHT
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL							
Goodard, K.H. 861		P/O	AUS422655	FI	Nil		NO.	DATE						
Jenkins, J.B. 668		LAC	1315686	PP	Nil		A6	12-8						
Wright, T.E.F. 861		LAC	RL63053	PP	Nil		D 14 (REVISED)							
							NO.	CHECKED						
							3	<input checked="" type="checkbox"/>						
							#41							
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				342							
Wasp	42-1205/21129 Nil		INST.	NIGHT	ON TYPE		TOTAL							
Wasp	42-10517/23009 Nil				SOLO	DUAL	SOLO	DUAL						
			43	29	140	100	186	156						
			16	17	45	58	85	103						
			7	5	-	1	30	38						

ACCIDENT CLASSIFICATION

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STAT BY  
FATAL  
INI.  
INJURY  
3RD  
5



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Formation exercise.

Nil

NATURE OF ACCIDENT:

A/c FS668 taxied into A/c FE861  
which was parked.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*MULT.  
TCA/PCT ✓  
TCA/XA*

CLASSIFICATION:

~~3. Hitting other aircraft.~~ 9

*9. Collision*

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: