

ACCIDENT CLASSIFICATION

UNIT No. 34 S.F.T.S. Medicine Hat.		COM. # 4	PLACE Rl Holson.		DATE 15-8-43	TIME 1745			
A/C TYPE Harvard IIB		No. FE915	CRASH CAT. D 1/72		S.E. X	M.E.	DAY X	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Teesdale, J.A.		SGT	1335899	FI	Nil		No.	DATE	
Van Dongen, C.		LAC	1649958	PP	Nil		D 14 (REVISED)		
							No.	CHECKED	
							22	<input checked="" type="checkbox"/>	
							No. 84		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wasp R1340-AN-1		21832/42-9493		INST.	NIGHT	ON TYPE		TOTAL	
		Nil				SOLO	DUAL	SOLO	DUAL
				-	-	749	98	782	149

1 accident

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT


CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATARY
FATAL
INJ.
INJURY 3rd
INJURY 5th



PURPOSE OF FLIGHT:

Essential dual.

NATURE OF ACCIDENT:

Tail wheel tyre burst while taxiing.

TECHNICAL OFFICER'S REPORT:

~~No technical failure.~~ Tyre burst. after life of
100 hours 5 min.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

T/O / UTWF

CLASSIFICATION:

15. Tyre failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL