

ACCIDENT CLASSIFICATION

UNIT No. 34 S.F.T.S.
Medicine Hat.

COM. # 4

PLACE M.A.

DATE 19-8-43

TIME 0130

H.Q. FILE

A/C TYPE Harvard II

No. 2805

CRASH CAT. D 1/72

S.E. X

M.E.

DAY

NIGHT X

COMMAND

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

Switon, L.

F/S 780519

FI Nil

NO.

DATE

Bauer, J.

LAC 788248

PP Nil

D 14 (REVISED)

NO.

CHECKED

30

No. 88

MONTH

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT BY
FATAL
INJ.
3rd
5

STAGE OF FLIGHT

Incident.

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Wasp S3H1

12173/A262243 Nil

INST.

NIGHT

ON TYPE

TOTAL

SOLO

DUAL

SOLO

DUAL

31

111

940

2

1400

37

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Instructional night flying.

TECHNICAL OFFICER'S REPORT:

~~_____~~ Tail wheel tyre burst.
after life of 92 hours.

NATURE OF ACCIDENT:

Tail wheel tyre burst while taxiing
at night.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TUC/UTWF

CLASSIFICATION:

15. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL