

ACCIDENT CLASSIFICATION

UNIT No.34 S.F.T.S.  
Medicine Hat.

COM. # 4

PLACE R 1 Holsom.

DATE 21-8-43 TIME 1130

H.O. FILE

A/C TYPE Harvard IIB

No. FE912

CRASH CAT. D 1/72

S.E. X

M.E.

DAY X

NIGHT

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

Coll, A.E.

F/O

136415

FI

Nil

NO.

DATE

Jounen, J.C.J.

LAC

1424923

PP

Nil

D 14 (REVISED)

NO.

CHECKED

39

No.93

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Wasp R1340-AN-1 42-9490/21829

INST.

NIGHT

ON TYPE

TOTAL

Nil

-

-

100

95

140

135

ACCIDENT CLASSIFICATION

COMMAND

MONTH


STAGE OF FLIGHT

FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
FATAL  
INJ.  
3rd  
INJURY

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Essential dual.

TECHNICAL OFFICER'S REPORT:

Tail wheel tyre burst after life of 88 hours.

NATURE OF ACCIDENT:

Tail wheel tyre burst while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TUC / UTWF

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL