

61		60		59		58		57		56		55		54		53		52		51		50		49		48		47		46		45		44		43		42		41		40		39		38		37		36		35		34		33		32		31					
ACCIDENT CLASSIFICATION																																																																	
UNIT 34 S.F.S.S. Medicine Hat		COM. 4		PLACE Holston, RI aerodrome		DATE 29-8-43		TIME 1115		H.O. FILE 1300-AJ961		S.E. X		M.E.		DAY X		NIGHT																																															
A/C TYPE HARVARD II				NO. AJ961		CRASH CAT. "D"2		S.E.		M.E.		DAY		NIGHT																																																			
PERSONNEL				RANK		NUMBER		DUTY		INJURIES				SIGNAL																																																			
Lidgeon, D.A.				F/O		115723		PP		Uninj.				NO.		DATE																																																	
														D 14 (REVISED)																																																			
														NO.		CHECKED																																																	
														53		✓																																																	
																#136																																																	
ENGINE		ENGINE NUMBER (S)				HOURS FLOWN BY PILOTS																																																											
Wasp S3-HI		4167/8148				INST.		NIGHT		ON TYPE				TOTAL																																																			
										SOLO		DUAL		SOLO		DUAL																																																	
						-		-		35		55		80		95																																																	
																115																																																	
ACCIDENT CLASSIFICATION																																																																	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		RAF		M		N	

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

4
2
1
7
4
2
1
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
3RD
INJURY
5

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Precautionary landings.

Nil

NATURE OF ACCIDENT:

A/C ground looped on landing..

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LS/PSS ✓

CLASSIFICATION:

~~38. Ground loop~~

2 *Severing*

L

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

ACTION TAKEN:

Log book endorsed.