



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Night flying circuits and landing.

Tail wheel tire burst after life of 16 hours 5 min.

NATURE OF ACCIDENT:

Tail wheel burst while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*7/1/50*

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil