

## CASPIR Aircraft Accident Cards

---

**Serial:** FP831

**Title:** Avro Anson Mk. II serial:FP831 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1943-August-19. Anson II s/n FP831. This accident involved 1 person. Soden J

**Keywords:** RCAFAnson II,FP831,15 SFTS,15 Service Flying Training School,Aerodrome,1943-August-19,SodenRCAF L20

**Created:** 1943-08-19

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP831>



PURPOSE OF FLIGHT:

Night circuits

TECHNICAL OFFICER'S REPORT:

Nil

*CS/P-2*

NATURE OF ACCIDENT:

A/C swung as student opened throttles for take-off. A/C turned to left off runway and taxied over glide path indicator.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~9. Swinging.~~

*12. Swung*

*(12)*

SECONDARY OR CONTRIBUTORY FACTORS:

~~2. Hitting obstructions~~

ACTION TAKEN:

Nil