

		ACCIDENT CLASSIFICATION															
TYPE OF A/C	UNIT	38 S.F.T.S.		COM.	2		PLACE	M.A.				DATE	26-8-43		TIME	1800-43	
		Estavan										H.Q. FILE	1100-84-34				
TYPE OF UNIT	A/C TYPE	ANSON II D ANSON II			NO.	8434 8422		CRASH CAT.	"D"1 Nil				S.E.	M.E.	DAY	NIGHT	COMMAND
														X		X	
CATEGORY	PERSONNEL	Lippard, D.C.W.		RANK	Lac		NUMBER	1800237		DUTY	PP		INJURIES	Uninj.		MONTH	
TYPE OF FLIGHT													SIGNAL			STAGE OF FLIGHT	
													NO.	DATE			
												D 14 (REVISED)		FORCED LANDING			
												NO.	CHECKED				
												5		LANDING			
												#60					
		ENGINE	ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS						FLIGHT					
		Jacobs L6MB	17564/9033		Nil		INST.	NIGHT	ON TYPE		TOTAL						
			14137/25448		Nil				SOLO	DUAL	SOLO	DUAL					
			25407/9777		Nil		11	5	14	20	49	55					
			25165/9535		Nil												
		ACCIDENT CLASSIFICATION												STATRY			
														FATAL			
														INJ.			
														3RD			
														S			
														M 2			

PURPOSE OF FLIGHT:

Local solo practises.

TECHNICAL OFFICER'S REPORT:

Nil

Handwritten notes:
20/1/51
10/1/51

NATURE OF ACCIDENT:

Collided with parked a/c 8422 while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

3. Hitting other a/c

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Log book endorsed "Carelessness" and grounded for 1 month