

PURPOSE OF FLIGHT:

Category test.

NATURE OF ACCIDENT:

Engine failure close to emergency 1
landing field and pilot landed.

TECHNICAL OFFICER'S REPORT:

Failure of hold down studs on #9 cylinder.

See findings

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil