

## CASPIR ARCHIVAL METADATA

---

<b>Serial:</b>	10719
<b>Title:</b>	Fairchild Cornell Mk. II serial:10719 Accident Card
<b>Author:</b>	Royal Canadian Air Force (RCAF)
<b>Subject:</b>	This accident involved 1 aircraft on 1943-August-23. Cornell s/n 10719. This accident involved 1 person. Weaver WJ
<b>Keywords:</b>	RCAFCornell ,10719,15 EFTS,15 Elementary Flying Training School,Aerodrome,1943-August-23,WeaverRCAF L20
<b>Created:</b>	1943-08-23
<b>Link:</b>	<a href="https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#10719">https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000434#10719</a>



PURPOSE OF FLIGHT:

Seq. 10,11,12,13,22.

NATURE OF ACCIDENT:

On levelling out, student allowed  
a/c to drift to left of runway.  
Port wing tip struck corner of  
control tower at side of runway  
damaging wing.

TECHNICAL OFFICER'S REPORT:

Nil LCO / 250

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~1. hitting obstructions.~~

6. collision

6

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil