



PURPOSE OF FLIGHT:

Per instruction. 1st Lt landings.

TECHNICAL OFFICER'S REPORT:

141

NATURE OF ACCIDENT:

500 engine failed at 300 ft. after take-off. Pilot completed circuit on one engine, losing height and landed on main as odrome with w/c retracted.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*L.B. / M. / P. / ...*

CLASSIFICATION:

~~13. Engine failure.~~

12. Forced Land

15

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. ...~~

26. Engine Trouble - Accident

26

ACTION TAKEN:

141