



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Night flying circuits and landings.

Tail wheel tire burst after life of 41.30 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil