



PURPOSE OF FLIGHT:

Armanent exercise.

NATURE OF ACCIDENT:

Tail wheel tire burst during landing run.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 34.40 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil