

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ944

**Title:** North American Harvard Mk. II / 2A serial:AJ944 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-September-09. Harvard IIB s/n AJ944. This accident involved 1 person. Murray VC

**Keywords:** RAFHarvard IIB,AJ944,41 SFTS,41 Service Flying Training School,Aerodrome,1943-September-09,MurrayRCAF L20

**Created:** 1943-09-09

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ944>

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32

ACCIDENT CLASSIFICATION

UNIT <b>No.41 S.F.T.S.</b> <b>Weyburn, Sask.</b>		COM. <b># 2</b>	PLACE <b>M.A.</b>				DATE <b>9-9-43</b>	TIME <b>2125</b>	
A/C TYPE <b>Harvard II</b>		No. <b>AJ944</b>	CRASH CAT. <b>C 1</b>		S.E. <b>x</b>	M.E.	DAY	NIGHT <b>x</b>	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
<b>Murray, V.C.</b>		<b>LAC</b>	<b>R174702</b>	<b>PP</b>	<b>Nil</b>		No. <b>A160</b>	DATE <b>10-9</b>	
							D 14 (REVISED)		
							No. <b>2</b>	CHECKED <input checked="" type="checkbox"/>	
							<b>#41</b>		
ENGINE <b>Wasp S3HI</b>		ENGINE NUMBER (S) <b>8471/4330 Slightly</b>		HOURS FLOWN BY PILOTS					
				INST.	NIGHT	ON TYPE		TOTAL	
						SOLO	DUAL	SOLO	DUAL
				<b>26</b>	<b>7</b>	<b>69</b>	<b>66</b>	<b>92</b>	<b>92</b>

COMMAND  
MONTH  
STAGE OF FLIGHT

7  
4  
2  
1  
7  
4  
2  
1  
FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJ. 3RD  
INJ. 5  
RAF M 2

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PURPOSE OF FLIGHT:

Solo night flying.

NATURE OF ACCIDENT:

Pilot failed to lower ~~w/o~~.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LUC/PEDUF/000L ✓

CLASSIFICATION:

~~34. Wheels up landing.~~

7. Others

7

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

32. w/c Drill - In Air 32.

ACTION TAKEN:

Log book endorsed "Gross Carelessness and pupil grounded for 1 month.