

62  
61  
60  
59  
58  
57  
56  
55  
54  
53  
52  
51  
50  
49  
48  
47  
46  
45  
44  
43  
42  
41  
40  
39  
38  
37  
36  
35  
34  
33  
32  
31

ACCIDENT CLASSIFICATION

UNIT 2 S.F.T.S. Islands, Ont	COM. 3	PLACE M.A.	DATE 2-9-43	TIME 1020
A/C TYPE HARVARD II	No. 2650	CRASH CAT. "C"2	H.Q. FILE 1100-26-50	S.E. X
			M.E.	DAY X
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Ellerent, G.A.E.	LAC	R186434	PP	Uni j.	No. DATE A.171 9-9
					D 14 (REVISED)
					No. CHECKED 2 <input checked="" type="checkbox"/>
					No.34

MONTH  
STAGE OF FLIGHT

4  
2  
1  
7  
4  
2  
1  
FORCED LANDING  
TAXYING  
LANDING  
TAKE OFF  
FLIGHT  
FATAL  
FATAL INJ.  
INJURY 3RD

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS			
		INST.	NIGHT	ON TYPE	TOTAL
Wasp S3H1	1289/Y134 Nil			SOLO DUAL	SOLO DUAL
		42	22	71 84	102 126

ACCIDENT CLASSIFICATION

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
RAF  
M  
Z

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

PURPOSE OF FLIGHT:

**Low level bombing.**

TECHNICAL OFFICER'S REPORT:

**Not technical failure.**

NATURE OF ACCIDENT:

**Aircraft swung on landing and ground looped.**

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*L 5 / 1755 ✓*

CLASSIFICATION:

~~61. Swinging on landing.~~

*2. Swing.*

*2*

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

~~24. Carelessness.~~

ACTION TAKEN:

**Personally admonished by Chief Instructor and Log Book endorsed for "Carelessness".**