

ACCIDENT CLASSIFICATION

UNIT	34 S.F.T.S. Medicine Hat			COM.	4	PLACE	M.A.		DATE	9-9-43		TIME	1000	
	A/C TYPE	HARVARD II			No.	2792		CRASH CAT.	"D"1/72		S.E.	x	M.E.	DAY
PERSONNEL		RANK	NUMBER	DUTY	INJURIES			SIGNAL		No.		DATE		MONTH
Teesdale, J.A.M.		SGT	1335899	PI	Uninj.									
Brazda, B.		LAC	788200	PP	Uninj.					D 14 (REVISED)				STAGE OF FLIGHT
										No.		CHECKED		
										18				FORCED LANDING
										#79				
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS								LANDING		
Wasp S3HI		Y206/5004 Nil		INST.	NIGHT	ON TYPE		TOTAL					TAKE-OFF	
				-	-	SOLO	DUAL	SOLO	DUAL			FLIGHT		
				-	-	814	99	846	149				STAT'RY	
				-	-	-	-	-	-			FATAL		
													INJURY	
												INJURY 3RD		
													INJURY 5	

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Local dual

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 20.30 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

15/1/2014

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

43. Tire trouble.

ACTION TAKEN:

Nil