

CASPIR Aircraft Accident Cards

Serial: FE915

Title: North American Harvard Mk. IIB serial:FE915 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-11. Harvard IIB s/n FE915. This accident involved 2 people. Morgan EJ, Pryde WG

Keywords: RAFHarvard IIB,FE915,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-11,Morgan,PrydeRCAF L20

Created: 1943-09-11

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE915>

61 () 60 () 59 () 58 () 57 () 56 () 55 () 54 () 53 () 52 () 51 () 50 () 49 () 48 () 47 () 46 () 45 () 44 () 43 () 42 () 41 () 40 () 39 () 38 () 37 () 36 () 35 () 34 () 33 () 32 () 31 ()

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 11-9-43	TIME 1140
A/C TYPE HARVARD IIB	NO. FE915	CRASH CAT. "D"1/72	H.Q. FILE 1300-FE915	
			S.E. x	M.E. x
			DAY x	NIGHT

COMMAND
7
4
2
1
7
4
2
1

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Morgan, E.J.	SGT	1579193	FI	Uninj.	NO.	DATE <input checked="" type="checkbox"/>
Pryde, W..G	LAC	1630350	PP	Uninj.		
					D 14 (REVISED)	
					NO.	CHECKED
					23	
					#8D	

MONTH
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATARY

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wasp S3HI	21832/42-9493 Nil	-	-	240	90	327	155
		-	-	-	-	-	-

STAGE OF FLIGHT
FATAL
INJ.
INJURY
3RD
5
4

1 () 2 () 3 () 4 () 5 () 6 () 7 () 8 () 9 () 10 () 11 () 12 () 13 () 14 () 15 () 16 () 17 () 18 () 19 () 20 () 21 () 22 () 23 () 24 () 25 () 26 () 27 () 28 () 29 () 30 () 31 () 32 () 33 () 34 () 35 () 36 () 37 () 38 () 39 () 40 () 41 () 42 () 43 () 44 () 45 () 46 () 47 () 48 () 49 () 50 () 51 () 52 () 53 () 54 () 55 () 56 () 57 () 58 () 59 () 60 () 61 ()

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Local dual exercise.

NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing.

TECHNICAL OFFICER'S REPORT:

Tail Wheel tire burst after life of 231.20 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

10704P

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil