

ACCIDENT CLASSIFICATION

UNIT 1 F.I.S. Trenton	COM. 1	PLACE M.A.	DATE 17-9-43	TIME 0025
A/C TYPE HARVARD II		NO. 3219	CRASH CAT. "C"2	H.Q. FILE 1100-32-19
		S.E. X	M.E.	DAY
				NIGHT X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Chandler, A.W.	P/O	J28517	PP	Uninj.	NO.	DATE
Martin, H.J.E.	P/O	R164508	P	Uninj.	A.115	17-9
Fortier,	LAC	R219449	Driver	Slightly Inj.	D 14 (REVISED)	
Cartier,	LAC	F139955	A C	Uninj.	NO.	CHECKED
					#87	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Wasp S3HI	4643/			SOLO	DUAL	SOLO	DUAL
		43	27	83	104	127	152
		44	30	68	108	112	158
							270

ACCIDENT CLASSIFICATION

COMMAND	4
	2
MONTH	1
	4
STAGE OF FLIGHT	1
	2
FORCED LANDING	
TAXIING	
LANDING	
TAKE-OFF	
FLIGHT	
STAT BY	
FATAL	
INJURY	
3RD	
5	
M	

PURPOSE OF FLIGHT:

Night flying.

NATURE OF ACCIDENT:

A/c collision with M.T. vehicle during night flying. Pilot did not see M.T. vehicle when taxiing to hangar. M.T. vehicle was without lights except intermittent red light which was very dim.

TECHNICAL OFFICER'S REPORT:

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TCO/XOV ✓

CLASSIFICATION:

~~2. Hitting obstruction.~~

9. Collisions

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil