

PURPOSE OF FLIGHT:

AJ586 Dual instruction on seq 6,7,& 8.
FE291 Cross Country - Solo Navigation

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

FE291 was doing a right hand circuit. From time he turned across wind until the red flare was fired Air Control pilot flashed a red aldis lamp. AJ586 had just touched down when red flare was fired in a/c FE291's path but came on down and landed on top of a/c AJ586.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

M: 25 ✓
20A/100
20A/100

SUMMARY No.

CLASSIFICATION:

~~45. Collision~~

6

6. Collisions

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

ACTION TAKEN:

ALA Parker was charged with an offence under Sec 39A Air Force Act on the 27th September, 1943 and awarded 14 days detention by the S.C.

C. G. LTD. 7084-43