

CASPIR Aircraft Accident Cards

Serial: FE325

Title: North American Harvard Mk. IIB serial:FE325 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-23. Harvard II s/n FE325. This accident involved 1 person. Botting RG

Keywords: RAFHarvard II,FE325,41 SFTS,41 Service Flying Training School,Aerodrome,1943-September-23,BottingRCAF L20

Created: 1943-09-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE325>

PURPOSE OF FLIGHT:

Precautionary landings.

TECHNICAL OFFICER'S REPORT:

No technical defects.

NATURE OF ACCIDENT:

Pilot held off too high, A/C struck ground. with starboard wing tip.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LH/TSMH ✓

CLASSIFICATION:

~~39. Flattening out too soon.~~

4 Heavy

4

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error~~

ACTION TAKEN:

Pilot's Log Book endorsed "Error of Judgment".