

CASPIR Aircraft Accident Cards

Serial: 2645

Title: North American Harvard Mk.II serial:2645 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-24. Harvard II s/n 2645. This accident involved 1 person. Dolphin RJJ

Keywords: RAFHarvard II,2645,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-24,DolphinRCAF L20

Created: 1943-09-24

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2645>

PURPOSE OF FLIGHT:

Night Circuits and landings

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Ground Looped on landing at night.
Started a swing on his third landing
took too violent corrective action
and A/C ground looped in opposite
direction.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

1.3/1.5

CLASSIFICATION:

38. Ground loop

SECONDARY OR CONTRIBUTORY FACTORS:

32. Pilot error

ACTION TAKEN:

Log Book endorsed