

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 13-9-43	TIME 1200
A/C TYPE ANSON II	NO. 7423	CRASH CAT. "D"1/32.	H.Q. FILE 100-74-23	
			S.E. x	M.E. x
			DAY x	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Firth, P.	SGT	1484104	SP	Uninj.	NO. DATE
Anthonsen, K.B.	E/L	1058	PP	Uninj.	
Ditmarsch, E.	LAC	1649949	PP	Uninj.	
<i>Incident</i>					D 14 (REVISED)
					NO. CHECKED
					28 <input checked="" type="checkbox"/>
					#23

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Jacobs L6MB	9673/25303	Nil					
	9062/17689	Nil					
		-	-	272	71	311	134

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY
3RD
5
RAF
M

PURPOSE OF FLIGHT:

Observer/Navigation exercise.

NATURE OF ACCIDENT:

Stbd tire burst while taxiing.

TECHNICAL OFFICER'S REPORT:

TUC / UTB

Stbd main-wheel tire burst after life of 62.50 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil