

CASPIR Aircraft Accident Cards

Serial: 7423

Title: Avro Anson Mk. II serial:7423 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-13. Anson II s/n 7423. This accident involved 3 people. Firth P, Ditmarsch E, Anthonsen KB

Keywords: RAFAnson II,7423,34 SFTS,34 Service Flying Training School,Aerodrome,1943-September-13,Anthonsen,Ditmarsch,FirthRCAF L20

Created: 1943-09-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#7423>

62 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 13-9-43	TIME 1200
A/C TYPE ANSON II	NO. 7423	CRASH CAT. "D"1/32.	H.Q. FILE 100-74-23	
			S.E.	M.E.
			DAY	NIGHT
			x	x

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Firth, P.	SGT	1484104	SP	Uninj.	NO. DATE
Anthonsen, K.B.	E/L	1058	PP	Uninj.	
Ditmarsch, E.	LAC	1649949	PP	Uninj.	
<i>Incident</i>					D 14 (REVISED)
					NO. CHECKED
					28 <input checked="" type="checkbox"/>
					#23

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Jacobs L6MB	9673/25303	Nil					
	9062/17689	Nil					
		-	-	272	71	311	134

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
5
RAF
M

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PURPOSE OF FLIGHT:

Observer/Navigation exercise.

NATURE OF ACCIDENT:

Stbd tire burst while taxiing.

TECHNICAL OFFICER'S REPORT:

TUC / UTB

Stbd main-wheel tire burst after life of 62.50 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil