

CASPIR Aircraft Accident Cards

Serial: 8392

Title: Avro Anson Mk. II serial:8392 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-September-23. Anson II s/n 8392. This accident involved 1 person. Evans L

Keywords: RCAFAnson II,8392,19 SFTS,19 Service Flying Training School,Between Purple Springs & 19 Service Flying Training School,1943-September-23,EvansRCAF L20

Created: 1943-09-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8392>

ACCIDENT CLASSIFICATION

UNIT 19 S.F.T.S. Vulcan	COM. 4	PLACE Track between Purple Springs & 19 SFTS	DATE 23-9-43	TIME 200
A/C TYPE ANSON II	No. 8392	CRASH CAT. "C"2	H.Q. FILE 11-00-83-92	
		S.E.	M.E.	DAY NIGHT
			x	x

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Evans, L.	LAC	F186080	FP	Uninj.	No. A.116	DATE 24-9
					D 14 (REVISED)	
					No. 3	CHECKED <input checked="" type="checkbox"/>
					#36	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS							
		INST.	NIGHT	ON TYPE		TOTAL			
				SOLO	DUAL	SOLO	DUAL		
Jacobs	F15721/1907 S15773/1958	Nil		16	6	14	23	47	54

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STRATRY

FATAL

INJ.

3RD

S


RAF

M

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

NO. 5 Navigation Cross Country.

TECHNICAL OFFICER'S REPORT:

Nil

1200/1002

NATURE OF ACCIDENT:

Low flying while on cross country.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~16. Unauthorized low flying or aerobatics.~~

23. Not Known

23

SECONDARY OR CONTRIBUTORY FACTORS:

~~17. Disobedience of Standing Orders.~~

18. Unauthorized Low Flying.

42

ACTION TAKEN:

Investigation to be carried out by the Unit.