

CASPIR Aircraft Accident Cards

Serial: 8330

Title: Avro Anson Mk. II serial:8330 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1943-September-28. They are: Anson II s/n 8418, Anson II s/n 8330. This accident involved 2 people. Millman JC, Stearn HD

Keywords: RCAFAnson II,8330,5 SFTS,5 Service Flying Training School,Aerodrome,1943-September-28,Millman,StearnRCAF L20

Created: 1943-09-28

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8330>

PURPOSE OF FLIGHT:

- (1) Seq. 25 (6,7,8)
- (2) Seq. 25 (6,7,8)

NATURE OF ACCIDENT:

Anson 8418 taxied into Anson 8330 parked at taxiing post. Pupil pilot negligently allowed A/C to move forward while doing pre-take off check.

TECHNICAL OFFICER'S REPORT:

No technical failure. *M. H. [unclear]*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other aircraft.~~

9. Collisions

SECONDARY OR CONTRIBUTORY FACTORS:

~~21. Carelessness.~~

ACTION TAKEN:

Log Book endorsed "Carelessness."

7 days detention.