

CASPIR Aircraft Accident Cards

Serial: 3569

Title: Fleet Fort serial:3569 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-September-10. Fleet Fort II s/n 3569. This accident involved 2 people. Mudge AW, Sutherland JA

Keywords: RCAF Fleet Fort II,3569,3 WS,3 Wireless School,Stevenson Field
Winnipeg,1943-September-10,Mudge,SutherlandRCAF L20

Created: 1943-09-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3569>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

W/T exercise.

Nil

NATURE OF ACCIDENT:

Afer landing on North runway a/c swung slightly to right off runway. Wheel tracks showed a/c rolled ahead and swung to left, when, hitting loose gravel at edge of runway, a/c skidded and stbd oleo leg buckled, coming to rest 90° across runway. Pilot unable to stop skid and swing by use of throttle and rudder.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~61. Swinging on landing.~~

2. Swung 2.

SECONDARY OR CONTRIBUTORY FACTORS:

~~44. Bad surface.~~

~~25. Inexperience.~~

ACTION TAKEN:

Nil