

ACCIDENT CLASSIFICATION

UNIT 31 O.T.U. Devert	COM. E	PLACE M.A.	DATE 30-9-43	0025 GMT			
A/C TYPE HUDSON III		NO. BW650	CRASH CAT. "B"	S.E.	M.E. X	DAY	NIGHT X
H.Q. FILE 1300-BW650			COMMAND				

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Burke, F.E.	GB SGT	1324210	P	Uninj.	NO. A.58	DATE 30-9
McRae, R.J.	AUS SGT	421495	N	Uninj.	D 14 (REVISED)	
Counihan, W.C.	NZ SGT	425833	WAG	Uninj.	NO. #9	CHECKED <input checked="" type="checkbox"/>
Scanlan, A.J.S.	NZ SGT	425468	WAG	Uninj.	MONTH	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Wright Cyclone	42-81405/152821	30	29	57	22	152	112
GE1820	A211289/39573			79		74	
G205A							

ACCIDENT CLASSIFICATION

COMMAND

MONTH


STAGE OF FLIGHT

- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- STATRY
- FATAL
- INJ
- INJURY
- 3RD
- 5

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Operational training flight.

Nil

acc/rep/01/0104

NATURE OF ACCIDENT:

Pilot landed on runway, having omitted to lower u/c.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~34. Wheels up landing.~~

7

7. Others

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

32. w/c Drill in air 32

ACTION TAKEN:

Loh book endorsed.