

CATEGORY		TYPE OF UNIT	TYPE OF A/C	ACCIDENT CLASSIFICATION										COMMAND	MONTH	STAGE OF FLIGHT
				UNIT No.3 B.G.S., Macdonald, Man.	COM. # 2	PLACE 12 mi. N. M.A.				DATE 10-9-43	TIME 0930					
				A/C TYPE Battle I		NO. 7476	CRASH CAT. A			S.E. x	M.E.	DAY x	NIGHT			
				PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL					
				Johnson, G.A.		SGT	R50190	P	Nil		No.	DATE				
				Olofson, G.W.		LAC	R192540	AG	Nil		N80	10-9				
				Olynik, J.		LAC	R210092	Ag	Nil		D 14 (REVISED)					
											No.	CHECKED				
											1	☒				
											#3					
				ENGINE	ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS								
				Merlin II	845/117598	seriously	INST.	NIGHT	ON TYPE		TOTAL					
										SOLO	DUAL	SOLO	DUAL			
							41	24	179	2	321	124				
				ACCIDENT CLASSIFICATION												

PURPOSE OF FLIGHT:

Gunner exercise.

TECHNICAL OFFICER'S REPORT:

Internal glycol leak.

NATURE OF ACCIDENT:

While carrying out gunnery exercise the engine failed emitting white then black smoke from exhaust. Pilot made wheels up landing in field.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~54. Engine failure in the air.~~

17

SECONDARY OR CONTRIBUTORY FACTORS:

~~34. Wheels up landing.~~

26. Engine trouble
Accident

ACTION TAKEN:

Nil