



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Authorized Low Flying Exercise.

Nil.

1200/1123

NATURE OF ACCIDENT:

On section low flying flew below leader at such a height that aircraft struck power line.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

22

CLASSIFICATION:

~~17. Disobedience of Standing Orders.~~

22. Collisions etc.

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

41. Disobedience of Orders

HI

ACTION TAKEN:

Pilot on charge. Remanded for summary of evidence.