

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

After return from transportation trip Right brake on ANSON AX367 was defective.
to Yarmouth.

NATURE OF ACCIDENT:

Anson was taxiing in a southerly direction on taxi strip. In attempting to turn slightly to left to follow path of taxi strip. It swung further than necessary and crashed into parked Hudson.

7/28/43

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~7. Brake failure.~~

9

Collision

SECONDARY OR CONTRIBUTORY FACTORS:

~~3. Hitting other a/c.~~

~~32. Pilot error.~~

ACTION TAKEN:

Pilot reprovred.

Brake Failure 36