

CASPIR Aircraft Accident Cards

Serial: FP902

Title: Avro Anson Mk. II serial:FP902 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1943-October-25. They are: Anson II s/n 8648, Anson II s/n FP902. This accident involved 2 people. Mutter NF, Jacobs GP

Keywords: RAFAnson II,FP902,33 SFTS,33 Service Flying Training School,Aerodrome,1943-October-25,Jacobs,MutterRCAF L20

Created: 1943-10-25

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP902>

PURPOSE OF FLIGHT:

Day solo flying practice.

TECHNICAL OFFICER'S REPORT:

Brakes found serviceable with exception of stbd main
brake on a/c 8648 which was not holding.

NATURE OF ACCIDENT:

A/C FP 902 was taxiing up side taxi-
ing strip on to the main tarmac and
parallel to hangars. A/C 8648 was
taxiing along main strip and the two
a/c collided at the junction. A/C FP 902
hitting port wing of a/c 8648.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

3. Hitting other a/c.

9

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Investigation.