

CASPIR Aircraft Accident Cards

Serial: 8301

Title: Avro Anson Mk. II serial:8301 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-October-28. Anson II s/n 8301. This accident involved 2 people. Lavin KE, Hill GR

Keywords: RCAFAnson II,8301,19 SFTS,19 Service Flying Training School,Bow River,1943-October-28,Hill,LavinRCAF L20

Created: 1943-10-28

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8301>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Navigation exercise No. 14 (Instrument
Triangle)

Nil

NATURE OF ACCIDENT:

Pilot was carrying out unauthorized
low flying over the Bow River when
a/c struck cable which stretched across
the river.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

22

16. Unauthorized low flying or aerobatics.

SECONDARY OR CONTRIBUTORY FACTORS:

- 41. Hitting obstructions.
- 24. Carelessness.

ACTION TAKEN:

Pending investigation.

42